ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura
Street ID	**Street Name**	**Significant Landmark**
W0122	NA	HMT Layout 2nd Block 6th Cross
Segment No.	**Total Length (m)**	
9/S-W0122/S052533	302.68	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	302.68	77.559149	13.079601	77.561781	13.078691	RI-A22	W0233

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains at HMT Layout 2nd Block 6th Cross and surrounding in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	2000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to drains at HMT Layout 2nd Block 6th Cross and surrounding in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-16-000014
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PET/60/2016-17	29/06/2016	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/06/2016	28/06/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
T.K.SHANKARAPPA		0.00
Phone No.	**E-Mail ID**	
9964440879		

Field Inspection Details

Number of Trees	Any Other Information	Name
15		JANARDHAN

Date of Inspection	Remarks
06/08/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	06/08/2016	05/09/2016	COMPLETED
SE	VASU K M	06/08/2016	05/09/2016	COMPLETED
EE	YARAPPA REDDY	06/08/2016	05/09/2016	COMPLETED
AEE	SHIVAKUMAR	06/08/2016	05/09/2016	COMPLETED
AE	JANARDHAN	06/08/2016	05/09/2016	COMPLETED
AE	JANARDHAN	06/08/2016	05/09/2016	COMPLETED